Easy Clocking Xenio 20 USB Scanner - *Download the Driver*

Step 1 You must be logged in as an administrator to successfully run the Download.

Step 2 In your Easy Clocking software, navigate to:

a. Settings
b. General
c. Biometric Devices
d. Enable Easy Clocking Xenio option

Step 3 Next, navigate to:

a. Users
b. Biometric Data
c. Select **Employee**
d. Select **Fingerprint**
    i. If Driver is not already installed, click ***Download Driver***

Step 4 Download the Driver (.Zip file) *(When using Chrome, choose "keep file," do not discard.)

Step 5 Extract the WebSensorConnectorXenio.ZIP file


a. Once extracted, open the file.
b. Navigate into the Platform folder and select your Operating System platform. (Choose from Windows64-bit, Windows86-bit or WindowsXP.)
c. After choosing your platform, right click on the application .EXE file called *dpinst.exe* and run this as an administrator.
d. Click ***Next***
e. Click ***Install***
f. Click ***Finish***


Step 6 Repeat Step 5-a.

a. From the file home, right click on the WebSensorConnectorXenio.EXE file and run this as an administrator.
b. Click ***Next***
c. Click ***Install***
d. Click ***Finish***

Step 7 Navigate to:

a. Users
b. Biometric Data
c. Select User
d. Select the finger you would like to enroll
e. Click Capture.


Fingerprint
Iris
CAPTURE


Fingerprint
Iris
CORRECT FINGER PLACEMENT
INCORRECT FINGER PLACEMENT
Place finger on scanner, please
Finger Image #1
Finger Image #2
Finger Image #3
Finger Image Quality
Very Good
Fair
Bad
Very Bad
CANCEL